



Tom  
Denison Mines (USA) Corp.  
1050 17th Street, Suite 950  
Denver, CO 80265  
USA

Tel : 303 628-7798  
Fax : 303 389-4125

www.denisonmines.com

December 27, 2010

Paul Baker  
State of Utah, Department of Natural Resources  
Department of Oil, Gas and Mining  
1594 West North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, Utah 84114-5801

RECEIVED

DEC 29 2010

DIV. OF OIL, GAS & MINING

Paul Baker:

Re: Submission of Annual Reports for Utah Permits, Denison Mines (USA) Corp., Tony M (M/017/0049), La Sal/Snowball (M/370/026), Redd Block Four (M/037/0046), Rim-Columbus (M/370/006), Pandora (M/037/012).

Denison Mines (USA) Corp. is providing annual reports for the above referenced mines. Maps these mines have not changed from the maps currently on file with you.

Please contact me (303) 389-4136 if you have any questions.

Respectfully.

A handwritten signature in cursive script that reads "Christy Woodward".

Christy Woodward, P.E.  
Environmental Coordinator  
Denison Mines Corp.

CC: Denison File  
Terry Wetz, Denison Mines (USA) Corp.  
Philip Buck, Denison Mines (USA) Corp.

Enclosure.



**STATE OF UTAH**  
**DEPARTMENT OF NATURAL RESOURCES**  
**DIVISION OF OIL, GAS AND MINING**  
 1594 West North Temple - Suite 1210  
 Box 145801  
 Salt Lake City, Utah 84114-5801  
 Telephone: (801) 538-5291  
 Fax: (801) 359-3940

**LARGE MINING OPERATIONS 2009 PROGRESS REPORT**  
**January 1, 2009 to December 31, 2009**

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

1. Mine Permit Number: M/037 10046
2. Mine Name: Redd Block IV
3. Name of Operator/Permittee: Demison mines (USA) Corp.

Note: If Operator's address, company representative or phone number have changed, please provide a replacement page for the Notice of Intention together with form MR-REV available on the Division's web page at [https://fs.ogm.utah.gov/pub/mines/minerals\\_related/forms/MR-REV.pdf](https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-REV.pdf).

4. Mine Location: Sec. 33, T28S, R24E
5. Report the gross amount of ore mined and waste moved, and the disposition of the materials (onsite stockpiles, sold, waste pile, regraded, etc.):

Gross Ore Mined 0 Tons, or 0 yd<sup>3</sup>  
 Waste Material Moved 0 Tons, or 0 yd<sup>3</sup>  
 New Disturbance 0 Acres during 2009  
 Area Reclaimed 0 Acres during 2009  
 Total Disturbed Area 8 Acres\*

\*Total mine disturbance from the beginning of mining operations through the end of 2009.

Was the ore shipped off site? If not, where is the ore located? N/A

Where is the waste located? N/A

6. Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE ([https://fs.ogm.utah.gov/pub/mines/minerals\\_related/forms/MR-SITE.pdf](https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-SITE.pdf)) to apply for full or partial bond/site release).

No reclamation was performed in 2010.

7. For large mines, include an updated map depicting surface disturbance and reclamation performed during the year (Rule R647-4-105). Updated maps were provided in an NOI amendment in 2010.

I hereby certify, under penalties of law, the information provided in this report is true and correct to the best of my knowledge and belief.

Name (Typed or Print): Philip Buck  
 Title of Operator: Vice President - Mining  
 Signature of Operator: Philip Buck  
 Date: 12/17/10